Fabrication Chart



Thicknesses of glass carried:



scale: 1:1 polish shown: FLAT

Other edgework:



MITER

BEVEL

Minimum fabrication chart:

Lami: 3/16 + .030 + 3/16

IG: 3/16 + 1/4 inch spacer + 3/16

Maximum fabrication chart:

Lami: 6 inches

IG: There is no maximum

Sandblasting terminology:

DIRECT READ

Sandblasting is on the first surface

READ THRU

Sandblasting is on the second surface (the artwork is flipped)

Other types of polishes not produced by A3:



BULL NOSE PENCIL OGEE WATER FALL

Insulated glass surfaces guide:



Note: Coated glass will always be on surface 2 or 3. Our spandrel glass is usually on 2 or 3 as well unless the customer would like it to be on Surface 4.